


NOTE:

THIS SPILL PLATE CATCH ASSEMBLY STARTS AT PAVER SERIAL NO. H-9084-B-D. FOR PAVERS PRIOR TO S/N H-9084-B-D REPLACEMENT PARTS WILL CONSIST OF REF. NOS. 2, 3, 4, 5, & 6.



HOLE LOCATION FOR PAVERS PRIOR TO H-9084-B-D.

| | | | |
|---|---------|---------------------------------|---|
| 7 | 500-825 | REPLACEMENT KIT | |
| 6 | 500-306 | HEX HD CPSCW 1/2-13 X 1 1/2" LG | 2 |
| 5 | 500-822 | FLAT WASHER 1/2 S.A.F. | 2 |
| 4 | 500-824 | SPILL PLATE CATCH | 2 |
| 3 | 500-823 | SPACER | 2 |
| 2 | 500-783 | HEX LOCK NUT 1/2-13 | 2 |
| 1 | 525-242 | PAVER HOPPER WELDMENT | 1 |

LAYTON MANUFACTURING COMPANY
SALEM, OREGON

TITLE: SPILL PLATE CATCH

Rev. 2/83

| | | | |
|--------------------|--|------|-------------------|
| <i>Ron Philips</i> | | NONE | DATE 7-1-80 |
| PAVER 525 | | | DWG. NO. C-328 |

| REF. NO. | PART NO. | DESCRIPTION | QTY. REQ. | REF. NO. | PART NO. | DESCRIPTION | QTY. REQ. |
|----------|----------|-------------|-----------|----------|----------|-------------|-----------|
|----------|----------|-------------|-----------|----------|----------|-------------|-----------|